

Technical Service Bulletin

Subject: Update BioGX version firmware and upgrade version number to Biogx-1.7.0.21	Date of Issue: 3/20/2024
	TSB Number: ANITSB - 0017

TSB Type:

Customer Option

Purpose:

Anitoo Updated the BioGX branded firmware to fix bugs and released as biogx-1.7.0.21.

Overview:

A bug is identified in the software that could cause early ct call. This is fixed in this release

Product(s) Affected:

MQ 4164 qPCR	MQ 4162 qPCR

Procedure:

- All updates are performed by Anitoo at Factory:

Anitoo fixed a bug that exists in all earlier versions of the software which could case an early ct call.

Verification:

- Description / instructions on how to confirm the updates were completed correctly.

1. Tested software on extensive list of previous test data to make sure the symptom has completely disappeared.

Additional Parts:

- N/A

Contact Information:

For additional information or guidance, please contact the Anitoo Product Support team:
info@anitoo.com.